

TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)

1. Name of the officer : ASSISTANT ENGINEER
LSGD SECTION, NENMANIKKARA G P
2. Name of School : JESUS ACADEMY SCHOOL THALORE
3. Period for which the certificate issued : 2022-2023
4. Nature of defect if any : NIL
 - a. Foundation and Basement : 12Nos - 6.10 x 6.10 x 3.60 m
 - b. Superstructure : 3Nos - 9.2 x 6.10 x 3.60 m
 - c. Door and Window : 7Nos - 6.10 x 6.10 x 3.60 m
 - d. Wood Work Wrought put up :
 - e. Roof :
 - f. Flooring :
 - g. Miscellaneous cracks, etc. :
5. Any major defects noticed which will Render the building unsafe if any manner : NA
6. Whether the maintenance works have been Done Properly : YES
7. Whether the structure is sound or not f : Sound under normal weather
conducting classes and Climate condition

Notes:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood, etc.
2. Any additional observations are seemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school inspected by me on 30/05/2023 and found to be ~~fit~~ unfit to conduct classes for the period 2022-2023 for the reason stated above.

Place : Paliyekkara
Date : 30/05/2023

Signature :
Designation :


ASSISTANT ENGINEER
Local Self Govt. Dep't
Nemanikkara Gram
Panchayat

